35.C5745 CIP/Contraction

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:

SEISHIRO YOSHIOKA ET AL.

Appl. No.: 08/479,000

Filed: June 7, 1995

For: DISPLAY DEVICE WITH

> ELECTRON-EMITTING DEVICE WITH ELECTRON-EMITTING REGION INSULATED FROM

ELECTRODES

U.S. Patent No.: 5,759,080

Issued: June 2, 1998 Examiner: J. Knapp

Group Art Unit:

June 30, 1999

The Honorable Commissioner of Patents and Trademarks Washington, D.C. 20231

> CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of

Gorrect 175080

100.00 OP

01 FC:145

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should be directed to our new address given below.

Respectfully submitted,

Registration No. 200

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

F501\A645775\mdf

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 5,759,080

: June 2, 1998 DATED

INVENTOR(S): SEISHIRO YOSHIOKA ET AL.

Page 1 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[54] TITLE

"FORM" should read --FROM-

[56] REFERENCES CITED

Other Publications "pat-" should read --Pat

COLUMN 1

Line 3, "FORM" should read --FROM--. Line 24, "et al" should read --et al.--.

COLUMN 2

Line 5, "have" should read --has--.X Line 22, "functional" should read --functioning--

COLUMN 3

Line 38, "stable." should read --state.--

COLUMN 4

Line 24, "illustrate" should read --illustrate an-

MAILING ADDRESS OF SENDER:

PATENT NO. <u>5,759,080</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

PRINTER'S TRIM LINE

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 5,759,080

: June 2, 1998 DATED

INVENTOR(S): SEISHIRO YOSHIOKA ET AL.

Page 2 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6

Line 24, "pattern. (See Fig. 1.)" should read --pattern (see Fig. 1.).--.



COLUMN 7

Line 30, "electrodes-supporting" should read --electrode-supporting--.

Line 37, "denotes" should read --denote-
Line 53, "these both" should read --both these--.



COLUMN 8

Line 7, "is" should read --are--. Line 25, "spacing," should read --spacing and--

COLUMN 9

Line 47, "are" should read --is--.



COLUMN 10

Line 17, "low melting" should read --low-melting.

Line 19, "t he" should read --the-
Line 45, "steps," should read --steps--.



MAILING ADDRESS OF SENDER:

PATENT NO. _5,759,080

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 5,759,080

DATED : June 2, 1998

INVENTOR(S): SEISHIRO YOSHIOKA ET AL.

Page 3 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11

Line 53, "um" should read $--\mu m--$.

COLUMN 12

Line 18, "FIGS. 14(A) to 14(E)" should read --FIG. 14(E)-Line 25, "(3) in FIG. 11." should read --FIG. 11C.--

Line 27, "step (4) in FIG> 11." should read --FIG. 11D. Line 43, "deviced" should read --devices--.

Line 64, "FIGS. 14(A-E)," should read --FIG. 14E,--.

COLUMN 13

Line 39, "FIG. 16," should read --FIGS. 16A and 16B, Line 40, "as" should be deleted.

Line 51, "commonly" should read --common,

COLUMN 15

Line 14, "Shown" should read --shown--.

Line 32, "through" should read --though--

Line 36, "has" should read --have--

Line 49, "has" should read --have--.

Line 67, "FIGS. 23,A) to D) " should read --FIGS. 23A-23I

MAILING ADDRESS OF SENDER:

PATENT NO. <u>5,759,080</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 5,759,080

DATED : June 2, 1998

INVENTOR(S): SEISHIRO YOSHIOKA ET AL.

Page 4 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 17, "(2) in FIG. 19." should read --FIG. 19B Line 19, "FIG. 19." should read --FIG. 19C.-

COLUMN 17

Line 4, "Layer" should read --layer--.

COLUMN 18

Line 31, "confirm" should read --confirmed--

Line 47, "3 a" should read --3a--.

COLUMN 20

Line 33, "materials," should read --material,

Line 44, "increase" should read --an increase-

Line 51, "most" should read --the most--.
Line 63, "are" should read --is--.

COLUMN 21

Line 15, "fact" should read --face--.

MAILING ADDRESS OF SENDER:

FORM PTO 1050 (REV. 3.82)

PATENT NO. <u>5,759,080</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 5,759,080

: June 2, 1998

INVENTOR(S): SEISHIRO YOSHIOKA ET AL. Page 5 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 22

Line 12, "FIGS. 3(a), (b) is" should read --FIGS. 3(A) and (B) are--. Line 49, "denotes" should read --denote--Line 66, "FIGS. 6(a), (b) is" should read --FIGS. 6(A) and (B) are--.

COLUMN 23

Line 6, "layer was" should read --layers were--. Line 10, "are" (second occurrence) should be deleted

COLUMN 24

Line 8, "inside" should read --the inside--.
Line 10, "an" should read --a--.
Line 34, "codes" should read --comes--.
Line 35, "forming" should read --forming of--

COLUMN 25

Line 56, "intergrated" should read --integrated-

MAILING ADDRESS OF SENDER:

PATENT NO. _5,759,080

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 5,759,080

DATED : June 2, 1998

INVENTOR(S): SEISHIRO YOSHIOKA ET AL.

Page 6 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 27

Line 21, "above" should read --above example--.

COLUMN 28

Line 51, "was" should read --were--.

8

COLUMN 30

Line 41, "a" (second occurrence) should read --an-

Line 61, "was" should read --were--.

COLUMN 32

Line 36, "as" should be deleted.

Line 44, "preparing" should read --prepared--

S.

MAILING ADDRESS OF SENDER:

PATENT NO. 5,759,080

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page

 \Rightarrow

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 5,759,080

DATED : June 2, 1998

INVENTOR(S): SEISHIRO YOSHIOKA ET AL.

Page 7 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 33

Line 3, "image" should read --of the--.



MAILING ADDRESS OF SENDER:

PATENT NO. <u>5,759,080</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

